


~~CONFIDENTIAL~~

Approved For Release 2005/08/22 : CIA-RDP87-01130R000100100006-3

17 NOV 1982


MEMORANDUM FOR: Chairman, Fine Arts Commission

FROM:

 Chief, Logistics Services Division, OL

SUBJECT: Headquarters Annex Committee Report

1. Attached is a list of problems in Annex facilities which are being addressed by this office. (U)



25X1

3. Many of the problems not addressed; i.e., selection of wall art, paint accents, broken furniture, drapery, signs and clutter are matters which affect specific offices. It is the responsibility of administrators in those areas to cite funds, process requisitions, and initiate any other coordination that may be necessary. LSD will be happy to assist offices needing assistance. (U)



25X1

Attachment

cc:



, FAC Annex Chairman  
SM&FB/LSD/OL  
/BSB/LSD/OL


OL 2 5245

25X1

WARNING NOTICE  
INTELLIGENCE SOURCE  
OR METHODS INVOLVED

Approved For Release 2005/08/22 : CIA-RDP87-01130R000100100006-3

~~CONFIDENTIAL~~



### Key Building

The owner/manager and the Agency will be conferring on the floor tile and carpet tile. The asphalt tiles are separating from the floor and the manager says the carpet tile is causing the problem. We cannot replace the carpet tile until the asphalt tiles are repalced or reglued.

The Building Manager has agreed to improve the condition of the fourth floor Ladies Room.

### Ames Building

Reception Room cubicles will be checked for light levels and if they are within GSA's 50 footcandles lighting criteria, they should not be increased due to energy conservation requirements.

Depot stock is being checked for availability of suitable furniture to be placed in the second floor lounges.

### Central Building

The heating/cooling systems have been under repair several times in recent weeks. New air filters have been installed by GSA to alleviate the roof problem.

The steam leaks have been repaired and GSA will be requested to replace all damaged ceiling tiles.

### East Building

The handrail on the Main Staircase was tightened. The area with loose tiles is now carpeted.

The air conditioner in the Men's Room drains into a set-tub. However, there are wash basins available for use in the same area.

### South Building

With the exception of a few areas of South Building, the building has been painted. A work order has been submitted to paint the remainder.

Overhead lights in the Ladies' Rooms have been replaced.

The building has recently been sprayed by an exterminator and GSA will be requested to provide a regularly scheduled vermin extermination program.

STAT

Approved For Release 2005/08/22 : CIA-RDP87-01130R000100100006-3

Approved For Release 2005/08/22 : CIA-RDP87-01130R000100100006-3

File

## ROUTING AND RECORD SHEET

SUBJECT: (Optional)

Headquarters Annex Committee Report

FROM:

EXTENSION

NO.

OL 2 5245

DATE

18 November 1982

TO: (Officer designation, room number, and building)

DATE

OFFICER'S INITIALS

COMMENTS (Number each comment to show from whom to whom. Draw a line across column after each comment.)

RECEIVED

FORWARDED

1. Attn: Bruce Johnson  
Room 2D00  
Headquarters

2.

3.

4.

5.

6.

7.

8.

9.

10.

11.

12.

13.

14.

15.